ROUNDABOUT THEATRE COMPANY

FINDING AID: SELWYN FOLDER 12

Collection Overview

Identifier: SELWYN_F 12

Inclusive Dates: 1999 - 2000

Extent: 1

Scope and Content

Flat plaster restoration/gypsum drywall, job numbers 9240, 9250. Includes steel framed gypsum lath and plaster partitions (9240.01-9240.02); plaster restoration (9242.02/1, 9242.06/1, 9242.09/1, 9242.10/1); fire shield (9250.01/1); Mr. Board moisture resistant gypsum board (9250.02/1); gypsum wallboard (9250.03/1); steel studs and runners (9250.04/1); and fiberglass duct liner board (9250.05/1).

Access Restrictions: Consult archivist for permissions. For detailed information regarding use of this collection, contact the Archives (archives@roundabouttheatre.org).

Parent Collection

Selwyn Theatre Historic Renovation - Architectural 1